

CERTIFICATE OF COMPLIANCE

Certificate Number E514608
Report Reference E514608-20200320
Issue Date 2022-JUNE-06

Issued to: SIEMENS ELECTRICAL APPARATUS LTD SUZHOU
455 ZHU JIANG RD SUZHOU NEW DISTRICT
SUZHOU, JIANGSU, 215129
CN

**This certificate confirms that
representative samples of**

RELAY SOCKETS AND ASSEMBLIES - COMPONENT
Models/Product

Have been evaluated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety: UL 508 & CAN/CSA C22.2 No. 14-18 , CSA C22.2 No. 14 - Standard for Industrial Control Equipment

Additional Information: See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Recognized Component Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product. [



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E514608
Report Reference E514608-20200320
Issue Date 2022-JUNE-06

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Relay sockets:

SYF08A or SYF08A1 or SYF08A2 or SYF08A4
SYF08A-E or SYF08A1-E or SYF08A2-E or SYF08A4-E
SYFK08F-E
SYW08B or SYW08C
SYF11A
SYF11A-E
SYF14A or SYF14A1 or SYF14A2 or SYF14A4
SYF14A-E or SYF14A1-E or SYF14A2-E or SYF14A4-E
SYFK14F-E
SYW14B or SYW14C
SKB08E
SKB14E
SSFK05F-E
SSFK08F-E
STF08A or STF08A1
STF08A-E or STF08A1-E
STW08B or STW08C
STF11A
STF14A
STW14C
SSF05F
SSF05F-E
SSF08F
SSF08F-E
SSW05
SSW08

Relay socket

SAF08A2
SAF08A2-E
SAP08F
SAP14F
SSP05F
SSP08F

Relay sockets: SAF14A1, SAF14A1-E]



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>

