Certificate Number E2 Report Reference E2 Issue Date 20

E233165 E233165-20190421 2022-JULY-15

Issued to: SIEMENS ELECTRICAL APPARATUS LTD SUZHOU 455 ZHU JIANG RD SUZHOU NEW DISTRICT SUZHOU JIANGSU 215129 CN

This certificate confirms that representative samples of AUXILIARY DEVICES - COMPONENT See addendum page for Models/Product

Have been evaluated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety: Additional Information: CSA-C22.2 No. 14 & UL 508 - Industrial Control Equipment See UL Product iQ[®] at <u>https://iq.ulprospector.com</u> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Recognized Component Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.

Bruce Mahrenholz, Conformity Assessment Director
UL LLC
Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions
contact UL Customer Service at http://ul.com/aboutul/locations/

Certificate Number E23 Report Reference E23 Issue Date 2022

E233165 E233165-20190421 2022-JULY-15

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Electromagnetic relays

PR, followed by 2, 3or4, followed by K, followed by P or Blank, followed by L or Blank, followed by T or Blank, followed by D, R or Blank, followed by -D6V through -D220V or -A6V through -A300V, followed by Blank or 2-10 Auxiliary code(Marked as required: to identify delivery information)

Socket

STF08A or STF08A1 STF11A STF14A STF08AE or STF08A1E STF14AE SKB08E SKB14E

Electromagnetic relays

SR, followed by1or2, followed by M or H, followed by P or Blank, followed by L or Blank, followed by T or Blank, followed by D, R or Blank, followed by –D6V through – D110V or -A6V through –A240V, followed by Blank or 2-10 Auxiliary code(Marked as required: to identify delivery information)

Socket

SSF05FE SSW05 SSF08FE SSW08

Sa Whill Bruce Mahrenholz

Bruce Mahrenholz, Conformity Assessment Director
UL LLC
Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions
contact UL Customer Service at http://ul.com/about/ul/ocations/



Certificate Number E23 Report Reference E23 Issue Date 2022

E233165 E233165-20190421 2022-JULY-15

Electromagnetic relays

ER、HR or NR, followed by 2、3or4, followed by E or C, followed by P or Blank, followed by L or Blank, followed by T or Blank, followed by D、R or Blank, followed by -D6V through -D220V or -A6V through -A300V, followed by Blank or 2-10 Auxiliary code (Marked as required: to identify delivery information)

NR2ML-D6 NR2ML-D12 NR2ML-D24 NR2ML-D36 NR2ML-D48 **NR2ML-D110** NR2ML-D220 NR2ML-A12 NR2ML-A24 NR2ML-A36 NR2ML-A48 NR2ML-A110 NR2ML-A220 NR2ML-A240 NR2MLD-D6 NR2MLD-D12 NR2MLD-D24 NR2MLD-D36 NR2MLD-D48 NR2MLD-D110 NR2MLD-D220 NR2MLR-A12 NR2MLR-A24 NR2MLR-A36 NR2MLR-A48 NR2MLR-A110 NR2MLR-A220 NR2MLR-A240 NR2MT-D6

Bathly Bruce Mahrenholz, Confe

Bruce Mahrenholz, Conformity Assessment Director
UL LLC
Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, p
contact UL Customer Service at http://ul.com/aboutul/locations/



Certificate Number Report Reference Issue Date E233165 E233165-20190421 2022-JULY-15

NR2MT-D12 NR2MT-D24 NR2MT-D36 NR2MT-D48 NR2MT-D110 **NR2MT-D220** NR2MT-A12 NR2MT-A24 NR2MT-A36 NR2MT-A48 NR2MT-A110 NR2MT-A220 NR2MT-A240 NR2MLT-D6 NR2MLT-D12 NR2MLT-D24 NR2MLT-D36 NR2MLT-D48 NR2MLT-D110 NR2MLT-D220 NR2MLT-A12 NR2MLT-A24 NR2MLT-A36 NR2MLT-A48 NR2MLT-A110 NR2MLT-A220 NR2MLT-A240 NR2MLTD-D6 NR2MLTD-D12 NR2MLTD-D24 NR2MLTD-D36 NR2MLTD-D48 NR2MLTD-D110 NR2MLTD-D220 NR2MLTR-A12 NR2MLTR-A24

Barnelly Bruce Mahrenholz, Confo

Bruce Mahrenholz, Conformity Assessment Director
UL LLC
Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact UL Customer Service at http://ul.com/aboutul/locations/



Certificate Number Report Reference Issue Date E233165 E233165-20190421 2022-JULY-15

NR2MLTR-A36 NR2MLTR-A48 NR2MLTR-A110 NR2MLTR-A220 NR2MLTR-A240 NR4FL-D6 NR4FL-D12 NR4FL-D24 NR4FL-D36 NR4FL-D48 **NR4FL-D110** NR4FL-D220 NR4FL-A12 NR4FL-A24 NR4FL-A36 NR4FL-A48 **NR4FL-A110** NR4FL-A220 **NR4FL-A240** NR4FLD-D6 NR4FLD-D12 NR4FLD-D24 NR4FLD-D36 NR4FLD-D48 NR4FLD-D110 NR4FLD-D220 NR4FLR-A12 NR4FLR-A24 NR4FLR-A36 NR4FLR-A48 NR4FLR-A110 NR4FLR-A220 NR4FLR-A240 NR4FT-D6 NR4FT-D12 NR4FT-D24

Barnelly Bruce Mahrenholz, Confo nity Assessment Director

UL LLC Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <u>http://ul.com/aboutul/locations/</u>



Certificate Number Report Reference Issue Date E233165 E233165-20190421 2022-JULY-15

NR4FT-D36 NR4FT-D48 **NR4FT-D110 NR4FT-D220** NR4FT-A12 NR4FT-A24 NR4FT-A36 NR4FT-A48 NR4FT-A110 **NR4FT-A220 NR4FT-A240** NR4FLT-D6 NR4FLT-D12 NR4FLT-D24 NR4FLT-D36 NR4FLT-D48 NR4FLT-D110 NR4FLT-D220 NR4FLT-A12 NR4FLT-A24 NR4FLT-A36 NR4FLT-A48 NR4FLT-A110 NR4FLT-A220 NR4FLT-A240 NR4FLTD-D6 NR4FLTD-D12 NR4FLTD-D24 NR4FLTD-D36 NR4FLTD-D48 NR4FLTD-D110 NR4FLTD-D220 NR4FLTR-A12 NR4FLTR-A24 NR4FLTR-A36 NR4FLTR-A48

Barnelly Bruce Mahrenholz, Confo

Bruce Mahrenholz, Conformity Assessment Director
UL LLC
Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact UL Customer Service at http://ul.com/aboutul/locations/



Certificate Number Report Reference Issue Date

E233165 E233165-20190421 2022-JULY-15

NR4FLTR-A110 NR4FLTR-A220 NR4FLTR-A240

Bra Mally Bruce Mahrenholz, Conformity Assessment Director

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at http://ul.com/aboutul/locations/



Page 7 of 7

UL LLC